Exhibit J

Case 107-CV-08561-LLS Document 14-5 Filed 04/01 MODEL #age 2 of 13

Case 1:07-cV-08661-LLS Docume	nt 14-5 Filed 04/01/2008 Page 2 of 13	
NYU	(1) TPAH15 & (1) TPAH18	
330 EAST 42ND STREET	(1) FC100-485-CF & (1) PPD-105-HX	
CARLYLE SPA	(1) 30AOLD30-SPC	
SAC CAPITAL MANAGEMENT	(1) 30AOLD30-S	
RIVER AIR	(1) FC100-230-CF, (1) PPD-50	
NEW YORK UNIVERSITY	(1) 37AOLM45-S, (1) PPD-100	
4 EAST 75 TH STREET	(1) 30AOLM48-S	
MARYKNOLL FATHERS	(1) 30A1SD280-SCF	
CARLYLE HOTEL – CAFÉ RENOVATION STORE	(1) FC100-173-CF, (1) FC36-352-SP	
GSK DATA CENTER	(MULTIPLE) FC96'S	
VALLEY NATIONAL BANK - 924 B'WAY	(2) FC100-173-CF	
SHEFFIELD APARTMENTS	(1) 20AOLD5, (8) 20AOLS13	
171 MACDOUGAL STREET	(1) TPAH-07	
122 GREENWICH AVENUE	(3) 34WOLM60	
PRESTIGE AIR TBD	(1) FC48-557	
AMERIPATH	TPAH-7-20-265-2	
TARRENT APPAREL CORP	30AOLM50-SFC	
THE LIMITED	(6) FC12-145-SP, (1) PPD-190	
HILLIER RTU REPLACEMENT	(2) TPAH-40, 20AOLM36, (1) TPAH-50, 20AOLM52	
HEWLETT PACKARD BRANCHBURG	(3) FC96-1195-SCP	
33 WHITEHALL STREET	FC48-502-SP	
SOROS-32ND FL	FC305S	
GHP	30WOSM240	
1500 BROADWWAY	TPAH-44-67-CF	
EQUINOX	FC96-859-SCQ	
NYU-19 W 42ND	FC36-DP, FC48-DP	
KJ / RAMAZ	TPAH-58, 30AOLM90-SPF	

1301 6TH AVENUE - LOBBY	PPD-300	
OTB Case 1:07-cv-08661-LLS Docum	ent 14-5 Filed 04/01/2008 Page 3 of 13 FC96-994-SCQP	
681 5TH AVENUE	(4) FC100-802-CF	
SJP PROPERTIES	TPAH08-20AOLD18	
LEGG MASON	30AOLM120-SPFC, 30AOLM120-SFC	
43 RD ST BUILDING	30WOLM72	
LUDLOW / ORCHIRD STREET	(4) FC100-658-SCF	
AMERIPATH	TPAH-7-20-265-2	
NY PRESBYTERIAN HOSPITAL	30A1SD120-SPCF	
KINGS COUNTY HOSPITAL	(3) 30AOSD160-SFCCF	
99 TH ST CONDO	(2) TPAH-28-30-500, TPAH-11-18-350	
501 7 TH AVENUE	30AOLM60-SFC	
HUDSON NEWS	(2) FC96-1612-SCQ, (2) FC96-1314-SCQ	
31 ST AVENUE CHILLERS	30AOLM150-SCP, 30AOLM150-SC	
107 WAVERLY	30AOLM15-SPCFQ	
REJAS HOTEL	TPAH-15	
57 TH STREET OVERBUILD	30A1SM340-SFCCF	
80 DEKALB	TPAH-15, TPAH-12, 20AOLD30, 20AOLD26	
605 WEST 42 ND ST	(2) 30AOLM180-SFQ & (1) FC36-392-SP	
MONACO	(2) 37AOLM45-SQPFC	
NASSAU COUNTY POLICE & FIRE COMMISSION	TPAH38	
828 FIFTH AVENUE	30AOLD30-SFC	
MSKCC	30AOLM330-SQPFC	
FORBES.COM	30AOLD30-SFC	
HUNTER COLLEGE	30AOLM45-SFC	
NYU	30A1SM280, TPAH-58-20AOCD80	
VERIZON	30AOLM135-SFC	
SALVATION ARMY	TPAH-18-30-650	

MLB	FC100-266-CF		
Case 1:07-cv-08661-LLS			
PETER COOPER	(3) 30AOLD28-SFCCF		
40 WALL STREET	(2) 30AOLM60-SCF, PPD-260		
RELATED COMPANIES	30AOLM150-SPFCCF		
200 WEST 72 ND STREET	(3) 30AOLM60-SFC, 30AOLM180-SFC		
SETON HALL	(2) TPAH-32-70		
ASTORIA	30AOLM45-SF		
WCS-CGC / BRONX ZOO	FC36-370-SPC		
MASTERCARD BOARD ROOM	20AOLD20		
AMERICAN AIRLINES	TPAH22		
RESIDENCE OF THE SECRETARY TO THE UN	33AOLD30		
LIBERTY TOWERS	FC100-375-SCF, FC36-442-SP		
KINGS COUNTY HOSPITAL	30AOLM104-SPF, FC96-1350-SPC		
KKR FINANCIAL	20AOLM70-SCF		
CITIBANK	(2) 34WOLM52-S		
METHANY PHARMACY	30AOLD15, PPD-29		
BRISTOL MYERS SQUIBB	34WOCM75, 34WOCD40, 34WOCD90		
CHARTER SCHOOL	30AISD140-PPD		
COUNT BASIC	(2) 20AOCD80, (1) 20AOLD18, (4) 20AOLD20, (1) 20AOLD30, (2) 20SOLD15, (2) 20AOLD10, (1) 20AOCD60, (1) 20AOLS8 & (1) 20AOLS3		
957-961 1 ST AVENUE	(1) 30AOLD30, (1) TPAH-12		
NYU	(1) 37AOLM60		
ALLSTON & BIRD	FC96-2287 / 37AOLM150		
57 IRVING PLACE	30AOLM165		
CBS RADIO	30AOLM90		
CARNEGIE 57	MULTIPLIER FC-100 DRY COOLERS		
CHRIST CHURCH	(1) FC100-1351-SCQP		

CON EDISON REPLACEMENT	(2) FC96-2334-S & (2) PPD471	
Case 1:07-cv-08661-LLS D	Occument 14-5 Filed 04/01/2008 Page 5 of 13 (1) 30AOISM280	
LOCATION #5	(1) 2A0LM45	
AKF OFFICES	(1) FC100-485-CF & (1) PPD-105-HX	
CHELSEA VETERINARY HOSPITAL	(1) FC48-502-SP	
GRACIOUS HOMES	(1) TPAH-12 & (1) 20AOLM15	
FLUSHING TOWN CENTER	(4) TPAH-7, (1) TPAH-38, (2) TPAH-28, (2) TPAH-5	
	(1) TPAH-32, (1) TPAH-58, (3) TPAH-18	
FLUSHING TOWN CENTER	(2) TPAH-8, (1) TPAH-24, (1) TPAH-7, (1) TPAH-44	
	(1) TPAH-28	
нвк	(1) 30AOLDM-SPT	
THE EDGE	(2) FC96-753-SCP & (2) FC96-1505-SCP	
CHENFELD RESIDENCE	(1) ESTATE-EWC-AC1-FD18-H2	
LIBERTY TOWERS-COOK ST	(1) FC36-DP	
NYU-PHASE II	(1) 30AOLM52-SPTFCQ407	
BDG-EMPIRE STATE BUILDING	(1) 30AOLM90-SPFC	
122 GREENWICH AVENUE	(1) 34WOLM60	

Exhibit K

LARRY HUDSON <LARRYH@rae-corp.com>

Thu, Jan 18, 2007 at 4:55 PM

To: JIM TEMPLE <iitemple@gmail.com>

Cc: SAM JONES PDA <SAM.JONES@rae-corp.com>, MICHAEL MCKAY <MICHAELM@rae-corp.com>, ERIC SWANK <ERICS@rae-corp.com>, JIM WILSON <JIMW@rae-corp.com>, ADAM MEYER <ADAMM@rae-corp.com>, MIKE CONTI <mikec@rae-corp.com>

Jim,

I'm scheduling Duane Conditt to fly out to Islip next Monday AM and drive into the city. He will be there for the installation of the heaters. We will also need Harbour there for tools etc. I guessed that would be Derek since he removed the heaters. Once all of the details are lined out I'll send you a formal itinerary.

In reference to the hoods I see Mike is sending a parts order through on these. My problem is that no one will take time to look for these in the field if they don't locate them quickly, they (and yourself) automatically jump to the conclusion that we made the mistake. We are getting the name of the person who received the hoods on site and signed for them. We are also confirming the number of hoods. If we do confirm all was shipped correctly either the customer or DNT will be paying for the additional hoods including the freight to get them there.

I will also be sending you information from the National Gas Code Book and Heatco regarding the venting of the heaters. It is our contention that this was done correctly at our factory. The fact that the units were mounted too close to walls in the field is a field issue, not ours.

As soon as I have Duane's trip info. I'll send you a copy via email.

Regards,

Larry

From: JIM TEMPLE [mailto:jjtemple@gmail.com]
Sent: Thursday, January 18, 2007 10:39 AM

To: MICHAEL MCKAY

Cc: SAM JONES PDA; LARRY HUDSON; CHUCK RUSSELL; WES MORGAN; CLIFF MINES; JIM WILSON; JAY

KINDLE; JEREMY COLVARD

Subject: Re: hoods

http://mail.google.com/mail/?ui=2&ik=74c3584fdd&view=pt&q=ethical%20drive&search... 3/28/2008

are coming from but i have repeated myself over and over. i sent pictures and drawings. if you want to get paid for the missing hoods, then prove they were shipped. Gacking slips with 28 Roots proves that you shipped 28 hoods. how many hoods were required for RTU-3 thru RTU-11? telling the customer to look harder is not an option. either you didn't send them & owe them or the customer lost them & he has to pay for them.

instead of waisting time=money argueing over this you could have shipped the missing/lost hoods with the hoods that were just built because they were not manufactured incorretly.

we are starting to look really bad on this job:

- 1. heaters not vented properly
- 2. hoods oversized and poorly constructed
- 3. hoods that don't fit and clearly were never attached in testing
- 4. dangerious and leaky doors on the supply side of the fan, positive pressure doors should open in
- 5. no conduit connecting the control panels for field control wiring, we were backcharge from control contractor
- 6. heater section fell apart due to poor design of support system
- 7. fixed sheaves on the blowers (even the small ones), very odd as is doesn't allow for balancing
- 8. i'm out o fthe office and working form memory, there is more.

who ever is paying attension, please help as this project is going down the toilet.

jim temple

On 1/18/07, MICHAEL MCKAY < MICHAELM@rae-corp.com > wrote:

Jim

http://mail.google.com/mail/?ui=2&ik=74c3584fdd&view=pt&q=ethical%20drive&search... 3/28/2008

together a parts order for any that are missing. We must account for the hoods on the shipping list before we can go formati. We first had being of the plant for the hoods on the shipping list before we can go formation that the first had being of the plant for the hoods on the shipping list before we can go formation that the first had being of the hoods had being on the packing and the first had been something but as to quote you, "if it is not written it did not happen". The idea about the ea hoods was that you identified those hoods particularly and blanketed the statement about all hoods missing and I informed you that they have to be in the holding yard and someone needed to look for them. The only hoods in question after that was the ea hoods. Please forwarded me pictures of the hoods on the packing slip and I will go from there.	
[Quoted text hidden]	

Exhibit L

- LIHKLEI KOIM	1/ // 631-	351-2466
Case 1:07-cv-08661-LLS E	Oocument 14-5 Filed 04/01/20	008 Page 11 of 13
(In Smaller	NH 631)))))
m Manuer	$\mathcal{N} \mathcal{N} \mathcal{N} \mathcal{N} \mathcal{N} \mathcal{N} \mathcal{N} \mathcal{N} $	
3 CAAIG KOSTELLO	H.H. 631-	751 -2270
(Richard Meiss Ner	NH 121 7	C1- フョフカ
(4) Elephon Merss Wer	2 HH. 631-3	3/20/0
6 Tim bomax	TRANK	718-269-3650
6 Colew P. Band	MATRIX MEUS COL	00 00 00
	win head bleat con	4. 718-727-0900
D Anthony Lovetro	Matrix mech	C-718-753-2596
/	•	
(8) MING QUOCK	NS. LIJ. HENCU STSCHM	718.470.8765
@ JoHNOBRIBLIO	BARY BARR	631-760-2102
701140DUANT	PIR I IMPE	031 100 0102
C Rosan Rocasus	BARR+BARR, In	- 912-1116-7018
(10) Rozano Reservice	DHOL+ MADO, IN	c 917-418-7078
	01500	0,000 = 0 = 0 = 0
(1) Chuck Russell	RAE-COIP	918 875 7222
(12) Kendall Kilverra	RAE-Corp	(918)825 7227
	,	
Extendall Kilvega (13) Jim Temple (15) Sov LEE	DNT	(212) 682-0747
	CA	2/2 615 3759
(1) IN UT		40 015 775)

Case 1:07-cv-08661 LLS Document 14-5 Filed 04/01/2008 Page 12 of 13

- (1) JUHN SIFDLECKI EMPIL OF 4/15/04
 - a) CHILLER # 1 NOT CRERATIONAL FLOW SWITCH
 - 6) ass?
 - c) CHILLAR & 2 LFAKS
 - d) CHILLER #Z COMPRESSOR #3 TRIPS
 - e) CHILLER #2 TOUGLE SWITCH COUFR MISSING
 - f) PIRE COVERING FOR HEAT TRACE NOT CONPLETE
- (2) DNT EMAIL 3/4/05
 - a) LOW AMBIENT SPRAYS PROFETOWERK.
 - 5) CONTROLS FOR LOW ANSIENT TIES (NTO BINS.
 - c) controls for Blowfor motors THES INTERMS.
- (B) MATRIX LAR 1/31/05 RE EWOIDS
 - a) REPAIRS TO CHILLAS
 - is) PREMETERS WWTER OPNS -
 - c) ANT Submittel -
 - 1) UNLONDING COMPRESSOR
 - 2) Auto Surp Drans.
- (4) COOVIT ENT -
- B) WARRANTY ISSUES_

Exhibit M